## North America Emission Control Area Fuel Oil Non-Availability Report
## ECA0100
## 1 2
##
(Include Double Pound for comments not form fields)
##Report Form ID Ship Operator Name
Oldendorff Carriers GmbH & Co. KG

3 4 5 6 7

Vessel Name Flag Country IMO ID Number Date of ECA First Notice Location of ECA First Notice Alam Sinar Singapore 9674816 21-Jan-14 Shipyard Shikoku, Japan

Shipyard Shikoku, Japan

Shipyard Shikoku, Japan

Name of Ports after First Notice Name of Last Port before ECA Entry Name of Port with Fuel Oil Supply Disruption Takamatsu

Number of Fuel Suppliers Contacted

13 14 15

Date of Entry in the ECA Time of Entry in the ECA Sulfur Content of Non-Compliant Fuel Oil 7-Feb-14 21:00 lt 2.3% HSFO

16 17 18

Projected Hours on Main Propulsion
1.3days = 31.2hrs

Name of First POC Compliance Fuel Oil Available at First POC?

Vancouver WA

yes

1	9	20	

Plan to Bunker Compliant Fuel Oil at First POC?	Number of fuel suppliers contacted at First POC
yes	1

Name of Second POC Compliant Fuel Oil at Second POC? Plan to Bunker Compliance Fuel Oil at Second POC? 

Vancouver BC - Plan to Bunker Compliance Fuel Oil at Second POC?

Number of Fuel Suppliers Contacted at the Second POC? Date of Exit from ECA? Time of Exit from ECA?

abt 17-Feb-2014

depending on load operations

Has this vessel operated in the ECA in previous 12 months? Number of Separate Visits to the ECA no

29 30 31

Number of Ports visited in the ECA Previously submitted ECA0100 forms? Number of Submitted Reports 0 no 0

32 33

Designated Corporate Official Name Designated Corporate Official E-mail Kat Mathias kat.mathias@oldendorff.com

Designated Corporate Official Phone Number 16046382333

Description of Actions to Achieve Compliance

Once we fixed the voyage to N America we tried to get LSFO at the shipyard, but were not able to arrange same i